



	Dimensional failure from supplier	Incorrect threadfit	Poor quality from supplier	Supplied incorrect part by supplier	Poor or incorrect finish	Supplier can't provide certs	
%age	32.26%	12.90%	32.26%	12.90%	3.23%	6.45%	